

REVISIONS				
ZONE	REV	DESCRIPTION	DATE	APPROVED
	A	工新字EG16028	04/24'17	Allen Chou

# INSTRUCTION SHEET

210

**1**

**2**

**3**

**4**

**5**

**3**

**4**

**5**

Strip approximately 7.7cm (3 inches) jacket from the cable.  
Be sure that the foil and/or braid remains intact.  
For Foil cables:  
Push the drain wire back over the cable jacket.  
For braided cables:  
Push the braid back over the cable jacket.

**5-1**

Fasten the cable to the strain relief tabs with cable ties and cut off the excess cable tie.

(正面)

**6**

**6-1**

**7**

**8**

**9**

**10**

Wiring diagram.

Terminate the wire with punch down tool make sure excess wire is cut off.

Screw up the back cover by screwdriver.

(背面)

UNLESS OTHERWISE SPECIFIED: TOLERANCES			PROJECT ID			
INCH	MM	ANGULAR	FILE	DATE		
$\pm .016$	$\pm .02$	$\times \pm 1'$	L4851.dwg			
$\times \pm .006$	$\times \pm 0.1$	$\times \pm .5'$				
$\times \pm .004$						
MATERIAL	DRAWN	CHECK	DATE	TITLE		
	Allen Chou		04/24'17	Instruction Sheet		
SURFACE	CHECK	APPROVED	SIZE	DRAWING NUMBER	PART NUMBER	REV
			A4	L4851	LL3A02101G	A
FINISH	APPROVED		SCALE	UNIT	SHEET	
			1:1	mm	1 OF 1	